

North Wilmot Church Timeline of Major Projects

2025

Cleared trees along north boundary & around horse sheds
Installed LCHIP plaque

2023

Repaired clapboard as needed
Painted exterior
Removed, repaired, painted & replaced shutters
Replaced repaired windows in sanctuary

2022

Raised & leveled structure
Replaced beam under bell tower
Installed concrete foundation - faced with antique granite
Replaced joists under pavilion
Replaced rotted trim & clapboard on east facade
Removed flower bed borders
Removed steps (3 granite & one concrete)
Increased grade in front of the building
Re-installed the two long antique granite steps (to return to circa 1915 configuration)
Installed concrete pads under two posts on west end of structure
Removed & repaired windows in sanctuary

2021

Removed asbestos-covered, non-functioning furnace & ducts

2017

Repaired & painted bell tower; replaced lower railing and rotted clapboards

2015

Painted lower window sashes - interior
Painted window sills & doors - interior
Replaced horizontal trim on north wall; added flashing - exterior

2012

Painted exterior
Repaired & painted shutters
Replaced two shutters on east front of bell tower
Rebuilt top railing on bell tower

2005

Installed standing seam metal roof
Tuckpointed top four courses of brick on chimney